



Paslode®
Impulse®

IM360*ci*





Paslode
Impulse



= 1250
(-5°C)



Paslode
Impulse



Ø 2.5 ▶ 3.1 mm
L 50 ▶ 90 mm (Smooth & Ring)
RoundDrive®
34°



Click



Paslode
Impulse



= 13000 max



OFF



ON



15 mn = 2500 max
60 mn = 10000 max
90 mn = 13000 max
2 mn = 200



○ ○ ○ ● 100%
○ ○ ● 75%
○ ● 50%
● 25%



● 0→300














BANG !


- 15 °C ➔ + 49 °C

1000/hour
4000/day


























.....







RESET



Notes



Notes

